



MASTER BOARD
MUST SET JUMPER BLOCKS
UNDER CPU IN 'A' POSITION

SLAVE BOARD
MUST SET JUMPER BLOCKS
UNDER CPU IN 'B' POSITION

Master to slave wiring

Matthew Millman

Sheet: /

File: mastertoslave.sch

Title: MCS-48 Temperature Sensor

Size: A4

Date:

KiCad E.D.A. kicad (5.1.6)-1

Rev: A

Id: 1/1